

方管组装机艺

RECTANGULAR DUCT
ASSEMBLY PROCESS

- ① 压筋 Grooving
- ② 共板法兰 TDF Flange
- ③ “C”形插条连接 “C”Type Clip Lock
- ④ 单、双骨连接 Male/Female Hem Lock
- ⑤ 插接法兰 TDC 法兰
- ⑥ 勾码 Clip
- ⑦ 东洋骨、单骨连接 Pittsburgh/Single Lock
- ⑧ 按扣骨拼接 Snap Lock
- ⑨ 弯头 Elbow Lock
- ⑩ “S”骨连接 “S” Lock
- ⑪ TDC 角码 TDC Corner
- ⑫ 角码连接 Corner Connection

